

Safe Use of 2-inch Hammer Unions for Oilfield Applications

API RECOMMENDED PRACTICE 7HU1
FIRST EDITION, MAY 2009

ERRATA, FEBRUARY 2014



AMERICAN PETROLEUM INSTITUTE

Copyright American Petroleum Institute
Provided by IHS under license with API
No reproduction or networking permitted without license from IHS

Safe Use of 2-inch Hammer Unions for Oilfield Applications

Upstream Segment

API RECOMMENDED PRACTICE 7HU1
FIRST EDITION, MAY 2009

ERRATA, FEBRUARY 2014



AMERICAN PETROLEUM INSTITUTE

Special Notes

API publications necessarily address problems of a general nature. With respect to particular circumstances, local, state, and federal laws and regulations should be reviewed.

Neither API nor any of API's employees, subcontractors, consultants, committees, or other assignees make any warranty or representation, either express or implied, with respect to the accuracy, completeness, or usefulness of the information contained herein, or assume any liability or responsibility for any use, or the results of such use, of any information or process disclosed in this publication. Neither API nor any of API's employees, subcontractors, consultants, or other assignees represent that use of this publication would not infringe upon privately owned rights.

Users of this Recommended Practice (RP) should not rely exclusively on the information contained in this document. Sound business, scientific, engineering, and safety judgement should be used in employing the information contained herein.

API is not undertaking to meet the duties of employers, manufacturers, or suppliers to warn and properly train and equip their employees, and others exposed, concerning health and safety risks and precautions, nor undertaking their obligations to comply with authorities having jurisdiction.

Information concerning safety and health risks and proper precautions with respect to particular materials and conditions should be obtained from the employer, the manufacturer or supplier of that material, or the material safety data sheet.

Work sites and equipment operations may differ. Users are solely responsible for assessing their specific equipment and premises in determining the appropriateness of applying the RP. At all times users should employ sound business, scientific, engineering, and judgement safety when using this RP.

API publications may be used by anyone desiring to do so. Every effort has been made by the Institute to assure the accuracy and reliability of the data contained in them; however, the Institute makes no representation, warranty, or guarantee in connection with this publication and hereby expressly disclaims any liability or responsibility for loss or damage resulting from its use or for the violation of any authorities having jurisdiction with which this publication may conflict.

API publications are published to facilitate the broad availability of proven, sound engineering and operating practices. These publications are not intended to obviate the need for applying sound engineering judgment regarding when and where these publications should be utilized. The formulation and publication of API publications is not intended in any way to inhibit anyone from using any other practices.

Any manufacturer marking equipment or materials in conformance with the marking requirements of an API standard is solely responsible for complying with all the applicable requirements of that standard. API does not represent, warrant, or guarantee that such products do in fact conform to the applicable API standard.

All rights reserved. No part of this work may be reproduced, translated, stored in a retrieval system, or transmitted by any means, electronic, mechanical, photocopying, recording, or otherwise, without prior written permission from the publisher. Contact the Publisher, API Publishing Services, 1220 L Street, N.W., Washington, D.C. 20005.

Copyright © 2009 American Petroleum Institute

Foreword

This recommended practice (RP) is under the jurisdiction of the American Petroleum Institute (API) Subcommittee on Drilling Structures and Equipment (SC8).

Nothing contained in any API publication is to be construed as granting any right, by implication or otherwise, for the manufacture, sale, or use of any method, apparatus, or product covered by letters patent. Neither should anything contained in the publication be construed as insuring anyone against liability for infringement of letters patent.

Shall: As used in a standard, “shall” denotes a minimum requirement in order to conform to the specification.

Should: As used in a standard, “should” denotes a recommendation or that which is advised but not required in order to conform to the specification.

This document was produced under API standardization procedures that ensure appropriate notification and participation in the developmental process and is designated as an API standard. Questions concerning the interpretation of the content of this publication or comments and questions concerning the procedures under which this publication was developed should be directed in writing to the Director of Standards, American Petroleum Institute, 1220 L Street, N.W., Washington, D.C. 20005. Requests for permission to reproduce or translate all or any part of the material published herein should also be addressed to the director.

Generally, API standards are reviewed and revised, reaffirmed, or withdrawn at least every five years. A one-time extension of up to two years may be added to this review cycle. Status of the publication can be ascertained from the API Standards Department, telephone (202) 682-8000. A catalog of API publications and materials is published annually by API, 1220 L Street, N.W., Washington, D.C. 20005.

Suggested revisions are invited and should be submitted to the Standards Department, API, 1220 L Street, NW, Washington, D.C. 20005, standards@api.org.

Contents

	Page
1 Scope	1
1.1 General	1
1.2 Objective	1
2 Terms, Definitions, and Abbreviations	1
2.1 Terms and Definitions	1
2.2 Abbreviations	3
3 Mismatch Description	3
3.1 General	3
3.2 Example of the Hazard	3
3.3 Mismatching 2-inch Figure 402, Figure 602 and, Figure 1002 with 2-inch Figure 1502	3
4 Description of the Engineering Design Solution	4
4.1 General	4
4.2 Reduced Thread Major Diameter	5
4.3 Raised Shoulder	5
4.4 Mark Indicating Design	5
5 Measures to Prevent the Make-up of Mismatched Components	6
5.1 General	6
5.2 Replace all 2-inch Hammer Union Components in Fleet to 2-inch Figure 1502	6
5.3 Go/No-go Gauges	6
5.4 Inspection and Marking	7
5.5 Training	8
5.6 Management of Change (MOC)	9
5.7 Permit-to-work (PTW) and/or Job Safety Analysis (JSA)	9
5.8 Job Site Inventory of Hammer Union Components	10
5.9 Color-coding	10
6 Mitigating the Effects of Mismatched Components Parting Explosively	10
7 General Safety Recommendations	10
7.1 General	10
7.2 Personal Protective Equipment (PPE)	10
7.3 Inspection, Maintenance, and Testing	10
7.4 Mixing Hammer Union Components from Different Manufacturers	11
7.5 Documented Safe Practices	11
7.6 Pressure Rating Consideration for Dynamic Conditions	11
7.7 Other Mismatch Combinations	11
7.8 System vs Component Pressure Rating and Service Application	11
7.9 Newly Manufactured Equipment not Conforming to New Engineering Design Solution	11
Bibliography	12
Figures	
1 Mismatched Male Union Sub and Wing Nut Threaded to a Female Union Sub	4
2 Reduction of External Thread Major Diameter	5
3 Raised Shoulder on New Engineering Design Compared to Original Design without Raised Shoulder	6
4 Marked Raised Shoulder on New Engineering Design Compared to the Original Geometry	7
5 Go/No-go Gauge Ring Not Accepting a 2-inch Figure 1502 Threads	8
6 Go/No-go Gauge Ring Accepting a 2-inch Figure 402, Figure 602, and Figure 1002 Threads	9

Copyright American Petroleum Institute
Provided by IHS under license with API
No reproduction or networking permitted without license from IHS

Safe Use of 2-inch Hammer Unions for Oilfield Applications

1 Scope

1.1 General

This recommended practice (RP) sets forth procedural recommendations as well as an engineering solution to the mismatching of a female 2-inch Figure 402, a female 2-inch Figure 602, or a female 2-inch Figure 1002 hammer union component (sub) with a male 2-inch Figure 1502 hammer union component (wing nut) as described in 3.2. The procedural recommendations described in this RP should be implemented to reduce further incidents.

The engineering solution, which prevents the mating of female 2-inch Figure 402, 2-inch Figure 602 and/or 2-inch Figure 1002 subs with the wing nut of the 2-inch Figure 1502 hammer union, applies to the manufacture of new hammer union components and should not be applied in the modification of existing hammer union components due to unknown factors caused by field wear.

1.2 Objective

The objectives of this RP are as follows.

- a) Raise awareness of the incompatibility of these hammer union components, whereby these components will mate improperly when threaded together; and are likely to fail explosively below the rated working pressure of the hammer union parts (male or female).
- b) Describe a recommended procedural solution to the industry that will reduce the likelihood of a 2-inch Figure 402, 2-inch Figure 602 and/or 2-inch Figure 1002 hammer union component being made-up inadvertently to a 2-inch Figure 1502 hammer union component. This procedural solution is critical because, depending on industry acceptance and implementation, the engineering solution might take years to effectively eliminate industry equipment manufactured to the original design of 2-inch Figure 402, Figure 602, and Figure 1002 hammer union components.
- c) Advise users and suppliers of hammer unions to adopt those procedural recommendations that are reasonably practicable to implement.

NOTE The recommendations in this document build on advice and advisories previously communicated to the industry.

- d) Describe an engineering design solution to the industry that makes impossible the mating of female 2-inch Figure 402, 2-inch Figure 602 and/or 2-inch Figure 1002 subs with the wing nut of the 2-inch Figure 1502 hammer union.
- e) Recommend users and suppliers of hammer unions implement this new engineering design on their job sites for 2-inch Figure 402, Figure 602 or Figure 1002 components. However, users should exercise caution in reintroducing 2-inch Figure 402, 2-inch Figure 602, and 2-inch Figure 1002 components if already banned from a company's fleet.

2 Terms, Definitions, and Abbreviations

2.1 Terms and Definitions

For the purposes of this publication, the following terms, definitions and abbreviated terms apply.

2.1.1**failure**

Mechanical separation of the female/male union components, especially under pressure, such that the equipment no longer is able to perform in the manner intended.

2.1.2**figure number**

A designation used by manufacturers of hammer union components to indicate the general design characteristics.

NOTE Depending on the manufacturer and specific design, figure number may represent pressure rating, specific geometric configuration of a union (e.g. flat-faced, misaligning, etc.), electrical insulating capability, etc. of the union type and its components.

2.1.3**incompatible**

Hammer union components that have the same nominal size, but different pressure ratings, materials and/or geometry.

2.1.4**inspection**

Comparison of equipment conformity to predetermined standards, followed by a determination of action required, if any.

2.1.5**maintenance**

Actions to include adjustments, cleaning, lubrication, and replacement of consumable components, as necessary to maintain the serviceability of the equipment.

2.1.6**manufacturer**

Individuals or companies manufacturing (or who have manufactured) equipment or materials covered by this RP.

2.1.7**mismatch**

Connecting hammer union components that have the same nominal size, but different pressure ratings, material and/or incompatible geometry.

2.1.8**testing**

Actions that are carried out on a piece of equipment to determine if that equipment can perform its intended function.

2.1.9**users**

Individuals or companies responsible for the use of equipment or material, or implementing recommended practices.

2.1.10**walk-the-lines**

The activity of checking the equipment directing the flow of fluid (from high pressure to low pressure) along each branch of the process ensuring that each item of equipment is suitably rated and matched to the physical and environmental conditions to which it is exposed by the operations.

2.2 Abbreviations

H ₂ S	hydrogen sulfide
HSE	health, safety, environmental
JSA	job safety analysis
MOC	management of change
PPE	Personal Protective Equipment
PTW	permit-to-work

3 Mismatch Description

3.1 General

The most common designations in the petroleum industry for hammer union components with the potential for mismatch, and which are covered by this RP are:

- 2-inch Figure 402,
- 2-inch Figure 602,
- 2-inch Figure 1002, and
- 2-inch Figure 1502.

These hammer union components have a history of failing under pressure due to incorrect matching of components (pressure ratings and/or incompatible geometry). The list of hammer union components that can be incorrectly matched is not meant to be all-inclusive. Users should establish controls to ensure hammer union combinations are safe, especially when more than one manufacturer's components are used.

3.2 Example of the Hazard

The mismatching of either the female 2-inch Figure 402, female 2-inch Figure 602 or the female 2-inch Figure 1002 hammer union component (sub) with a male 2-inch Figure 1502 hammer union component (wing nut) is a worldwide issue in the industry and can cause serious incidents, including fatalities. Complete and proper make-up of hammer union components is required to attain the rated working pressure of the equipment.


The root cause of the mismatch is that the 2-inch Figure 402, 2-inch Figure 602 and 2-inch Figure 1002 unions were designed with the same thread pitch as the 2-inch Figure 1502 and the female subs have a major (external) thread diameter that is just large enough to engage the minor (internal) diameter of the 2-inch Figure 1502 wing nut internal acme thread. Consequently, although these mismatched hammer union components (2-inch Figure 1502 wing nut with a 2-inch Figure 402, Figure 602 or Figure 1002 female sub) may fully make-up and hold some level of pressure, an explosive failure of the mismatched unions will occur well below the rated working pressure of any of the components, putting people and property at risk.

See IADC Alerts 98-01, 99-33, 00-15, 03-16, and 06-01 for additional information.

3.3 Mismatching 2-inch Figure 402, Figure 602 and, Figure 1002 with 2-inch Figure 1502

A 2-inch Figure 1502 wing nut can be threaded onto a 2-inch Figure 402, 2-inch Figure 602 or 2-inch Figure 1002 female sub as shown in Figure 1. Although the acme thread diameters are different, the pitch (number of threads per inch) is the same. The resulting mating overlap of the threads between these mismatched hammer union components

will not hold pressure. Consequently, the mismatch combinations will make-up and appear to be pressure tight (and may even hold significant pressure), however they will fail well below the rated working pressure of either of the union components (male or female). The failure will be explosive, putting people and property at risk.



Key

- 1 2-inch Figure 1502 wing nut
- 2 improperly made-up acme thread-hazardous!!!
- 3 2-inch Figure 1502 male sub
- 4 2-inch Figure 402/602/1002 female sub

Figure 1—Mismatched Male Union Sub and Wing Nut Threaded to a Female Union Sub

4 Description of the Engineering Design Solution

4.1 General

The recommendations described herein are intended to be an engineering solution to the mismatch problem by preventing the inadvertent make-up of a female 2-inch Figure 402, 2-inch Figure 602 or 2-inch Figure 1002 sub with the wing nut of the 2-inch Figure 1502 hammer union. Manufacturers are encouraged to implement this engineering solution on all newly manufactured hammer union components. Users should utilize components and assemblies that implement this solution.


The engineering design solution involves a change of the 2-inch Figure 402, 2-inch Figure 602 and 2-inch Figure 1002 female sub in three different areas as follows:

- a) reduced thread major diameter,
- b) raised shoulder,

c) mark indicating the design.

4.2 Reduced Thread Major Diameter

The major diameter of the external acme thread on the 2-inch Figure 402, 2-inch Figure 602 and 2-inch Figure 1002 female subs shall be reduced so as not to exceed, and thus not allow engagement with, the minimum minor diameter of the internal acme thread of the 2-inch Figure 1502 wing nut. Figure 2 illustrates a reduction of the external acme thread by comparing the original design major diameter (on left with no raised shoulder) with the reduced major diameter (on right with raised shoulder).



Key

- 1 illustration of reduction
- 2 old design
- 3 new design


Figure 2—Reduction of External Thread Major Diameter

4.3 Raised Shoulder

A raised shoulder shall be designed into the area behind the threads of the 2-inch Figure 402, 2-inch Figure 602 and 2-inch Figure 1002 female subs to provide a visual indicator of the redesign. This raised shoulder allows the users and suppliers to readily separate their inventory of hammer union components between the original design and the new design that is specifically redesigned to prevent mismatching. Figure 3 shows a comparison of the original geometry without the raised shoulder (on the left) vs the new geometry which incorporates the raised shoulder on the female sub (on the right) of the redesign, allowing for ready identification of the new engineering design that prevents mismatching.

4.4 Mark Indicating Design

The raised shoulder shall be permanently marked with the size and figure number of the hammer union component to provide additional visual indication of the new design. Figure 4 shows a comparison of a female sub of the new geometry, which incorporates the raised shoulder (on the left) vs the original geometry without the raised shoulder (on the right) with the size and figure number marking.



Key

- 1 old design
- 2 new design

Figure 3—Raised Shoulder on New Engineering Design Compared to Original Design without Raised Shoulder

5 Measures to Prevent the Make-up of Mismatched Components

5.1 General


The recommendations set forth herein are preventative measures intended, in the right combination for a given fleet or equipment package, to be a procedural solution to the mismatch problem. Users and suppliers of hammer union components should adopt one or more of these measures that are reasonably practicable for their operations.

5.2 Replace All 2-inch Hammer Union Components in Fleet to 2-inch Figure 1502

Until an industry design specification is developed, as an interim measure, users should consider replacing all 2-inch pipe work hammer union components to 2-inch Figure 1502 and eliminate all 2-inch Figure 402, 602 and 1002 hammer union components from their fleet.

5.3 Go/No-go Gauges

Go/no-go gauges should be used on all 2-inch female subs to determine whether the component is acceptable or unacceptable for use with a 2-inch Figure 1502 male sub and nut. As an example, the gauge shown in Figure 5 will “no-go” on a 2-inch Figure 1502 female sub deeming the component acceptable for use with a 2-inch Figure 1502 male sub and nut. However, the gauge will “go” on a 2-inch Figure 402, Figure 602 or Figure 1002 female sub as shown in Figure 6 deeming the component unacceptable for use with a 2-inch Figure 1502 male sub and nut.



Key

- 1 new design
- 2 old design

Figure 4—Marked Raised Shoulder on New Engineering Design Compared to the Original Geometry


Go/no-go gauges should be used routinely by regular users of 2-inch hammer unions. These gauges should be readily available on all rigs and job sites with 2-inch size unions. Field personnel should be trained in the use of the go/no-go gauges.

Contact union manufacturers for a listing of go/no-go gauge suppliers or refer to IADC Alert 99-33 for further information.

5.4 Inspection and Marking

Hammer union components should be regularly inspected and maintained based on manufacturer's recommendations and experience by the user. Union components that do not meet the manufacturer's minimum service recommendations shall be immediately removed from service. In addition to the manufacturer's recommendations, this inspection process should include gauging of 2-inch female hammer union components to determine the figure number, and marking these 2-inch female unions with the 2-inch Figure 402, Figure 602, Figure 1002, or Figure 1502 designation, thus allowing for ready identification. If a 2-inch female hammer union component is not marked, allowing ready and easy identification of the component, it should not be used until a go/no-go gauge is first used to identify the size and figure of the component and the correct identification is marked on the component.

Marking should be accomplished by either stamping or banding, but should be easy to read when walking-the-lines. Marking applies especially to plugs and instrument fittings or other pressure-retaining equipment with hammer union



Acceptable Female Sub for Use with 2-inch Figure 1502 Male Sub

Key

- 1 2-inch union gauge ring
- 2 2-inch Figure 1502 female sub

Figure 5—Go/No-go Gauge Ring Not Accepting a 2-inch Figure 1502 Threads


connections. Marking should be the primary means of identification. Competent personnel should carry out the inspection and maintenance procedures.

An inspection schedule should be developed and implemented based on experience, the manufacturer's recommendations and other factors including environment, regulatory requirements, operating time, testing, and repairs. Rejected hammer union components shall be marked to indicate their rejected status and removed from service.

NOTE Specific manufacturer's recommendations are not covered in this document; consult the manufacturers directly for these details.

5.5 Training

Users should train their field personnel, including supervisors, on the hazards of mismatched hammer union components and ensure this information is included in the training matrix for their field personnel. This training should cover recognition of the different hammer union figure types, recognition of union component markings, understanding what components are appropriate for what service, and use of the go/no-go gauge. Training should also include recognizing 2-inch Figure 402, Figure 602 and Figure 1002 female unions newly manufactured according to the engineering design solution described in Section 4. In addition, Health, Safety and Environmental (HSE) orientations for new/transferred staff should include a list of potentially fatal hazards, including mismatched hammer union components.



Unacceptable Female Sub for Use with 2-inch Figure 1502 Male Sub

Key

- 1 2-inch union gauge ring
- 2 2-inch Figure 402/602/1002 female sub

Figure 6—Go/No-go Gauge Ring Accepting a 2-inch Figure 402, Figure 602, and Figure 1002 Threads

Users should consider implementing an incentive program that rewards employees that identify and remove components that should not be in their fleet (e.g. 2-inch Figure 402, Figure 602 and Figure 1002 components in the fleet of a company whose policies dictate the use of only 2-inch Figure 1502).

5.6 Management of Change (MOC)

An MOC process should be utilized, including gauging and/or confirmation of markings correct for the service, if a hammer union component needs to be changed out in a system. This is to ensure the replacement does not result in a mismatch. When equipment (such as a manifold) that has been pre-manufactured (or pre-assembled) is in need of repair or replacement, the manufacturer/assembler's hammer union component specifications should be consulted to ensure correct unions are utilized for the repair/replacement. Users should maintain documentation of all hammer union components utilized in their permanent and temporary piping systems. This information should be reviewed and updated when repairing or replacing equipment.

5.7 Permit-to-work (PTW) and/or Job Safety Analysis (JSA)

A PTW and/or JSA process should be utilized for all jobs involving hammer union components. The PTW/JSA should include a walk-the-lines inspection before pressure testing prior to commencement of operations. This walk-the-lines inspection is especially important when temporary hammer union components from a contractor are being connected to installed hammer union components from another company. Inspection of all equipment interfaces (with different owners) should be conducted.

5.8 Job Site Inventory of Hammer Union Components

Users should maintain an inventory of hammer union components by job site and implement a system by which to identify/inspect any additional equipment with hammer union components that arrives on the job site. This inventory control process at the job site should help ensure no mismatches, which is especially important when temporary hammer union components in use by one company are being connected to installed hammer union components in use by another company.

5.9 Color-coding

Hammer union components should be color-coded by the user to indicate the union figure number or working pressure of the equipment. Users who opt to have such a color code should publish the code and make it available to all staff, suppliers, and customers. An example of a color-coding system can be found in Enform IRP 4 [6].

NOTE Color-coding should not be relied upon as the primary design identifier as it is not permanent (due to environmental exposure in field) and can easily be impacted by human error or conflict with other color-coding used in the field.

6 Mitigating the Effects of Mismatched Components Parting Explosively

The following mitigation measures should be considered and applied to protect people in the case of a mismatched hammer union or other component failure. Most, if not all, of these measures should be applied to every job utilizing hammer union components.

- a) Use barriers and/or restricted access of personnel for all pressurized operations. Place staff where they are minimally exposed.
- b) Orient outlet and instrumentation fittings at 90° or 180° to an employee's expected body placement when it is necessary for an employee to be near pressurized equipment (e.g. to operate valves or read gauges).
- c) Locate the temporary pipe connections where there is less exposure to personnel (e.g. under the rig floor).
- d) Use a system of restraint for pipework that has been proven in pressurized operations. Examples include fiber rope restraints and safety clamps with wire rope. Personnel should be trained in the proper installation of the safety restraint system.

7 General Safety Recommendations

7.1 General

The general safety recommendations for working with temporary piping, hammer unions, and/or union components described in 7.2 through 7.9 should be considered to help protect people and property. This list is not meant to be all-inclusive.

7.2 Personal Protective Equipment (PPE)

Proper PPE should be used during make-up and breakout of hammer union components. A hazard assessment should be performed to determine the proper PPE based on the specific equipment and tools being used.

7.3 Inspection, Maintenance, and Testing

Hammer union components should be inspected, maintained, tested, and removed from service (due to corrosion, erosion, damage, and deformation of wing nut ears) based on manufacturer's recommendations and experience by

the user. This should include, but not be limited to, inspection of the threads for excessive wear as a result of repeated make-up/break-outs.

NOTE Specific manufacturer's recommendations will not be covered in this document; consult the manufacturers directly for these details.

7.4 Mixing Hammer Union Components from Different Manufacturers

Users, as much as practical, should avoid mixing hammer union components from different manufacturers. Users should establish controls to ensure that if union components from more than one manufacturer become mixed in a union assembly or connection, the resulting combination is safe and not considered a mismatch.

7.5 Documented Safe Practices

Users and suppliers should have documented procedures that reflect safe practices for make-up/breakout, testing and use of pressurized temporary piping and hammer union components.

EXAMPLE Never attempt to tighten or loosen a pressurized union, as doing so could cause the union to disengage. Ensure that a union is not pressurized before hammering to tighten or loosen.

7.6 Pressure Rating Consideration for Dynamic Conditions

Users of hammer union components should consider the effect of pressure surges that might be additive to the maximum anticipated job pressure. Users should select appropriately rated pressure equipment and union connections to adequately control overpressure as a result of a pressure surge.

7.7 Other Mismatch Combinations

There are other possible mismatch combinations not covered by this document, as they are not commonly used in the petroleum industry, such as 1-inch, 1 3/4-inch, 3-inch and 5-inch mismatches. Manufacturers should review all of their products for this issue and advise users of which combinations are subject to this mismatch hazard. Users and suppliers should be familiar with these mismatch combinations as well.

7.8 System vs Component Pressure Rating and Service Application

Users and suppliers should understand the maximum pressure rating of the system, taking into account the lowest pressure rating of any one component and its intended service application [standard vs hydrogen sulfide (H₂S)], before commencing testing and/or operations. Specifically, the system maximum pressure rating must be set to that of the system's lowest rated component.

7.9 Newly Manufactured Equipment not Conforming to New Engineering Design Solution

Users should be aware that there could be some manufacturers that continue to produce 2-inch Figure 402, Figure 602 or Figure 1002 unions, or equipment with these unions, that do not conform to the new Engineering Design Solution (see Section 4 of this RP). Such unions and equipment will continue to be dangerous and users should exercise the preventative measures outlined in Section 5 of this RP.

Bibliography

- [1] IADC Alert 98-01 ¹, *High Pressure Lines and Hammer Unions*
- [2] IADC Alert 99-33, *More on Mismatched Hammer Unions*
- [3] IADC Alert 00-15, *Additional Serious Incidents with Mismatched Hammer Unions*
- [4] IADC Alert 03-16, *Mismatched Hammer Unions Still being Found*
- [5] IADC Alert 06-01, *Mismatched Hammer Union Results in a Fatality*
- [6] Enform IRP 4 ², *Well Testing and Fluid Handling*

¹ International Association of Drilling Contractors, 10370 Richmond Ave, Suite 760, Houston, Texas 77042, www.iadc.org.
² Enform Canada, 1538 – 25th Avenue NE, Calgary, Alberta, T2E 8Y3, Canada, www.enform.ca.

www.ihsonline.com



2009 Publications Order Form

Effective January 1, 2009.

API Members receive a 30% discount where applicable.

The member discount does not apply to purchases made for the purpose of resale or for incorporation into commercial products, training courses, workshops, or other commercial enterprises.

Available through IHS:

Phone Orders: **1-800-854-7179** (Toll-free in the U.S. and Canada)
303-397-7956 (Local and International)
Fax Orders: **303-397-2740**
Online Orders: **global.ihs.com**

Date: _____

☐ **API Member** (Check if Yes)

Invoice To (☐ Check here if same as "Ship To")

Name: _____

Title: _____

Company: _____

Department: _____

Address: _____

City: _____ State/Province: _____

Zip/Postal Code: _____ Country: _____

Telephone: _____

Fax: _____

Email: _____

Ship To (UPS will not deliver to a P.O. Box)

Name: _____

Title: _____

Company: _____

Department: _____

Address: _____

City: _____ State/Province: _____

Zip/Postal Code: _____ Country: _____

Telephone: _____

Fax: _____

Email: _____

Quantity	Title	SO★	Unit Price	Total
	Spec 7K, Specification for Drilling and Well Servicing Equipment		\$176.00	
	RP 7L, Inspection, Maintenance, Repair, and Remanufacture of Drilling Equipment		\$105.00	
	RP 8B, Inspection, Maintenance, Repair, and Remanufacture of Hoisting Equipment		\$80.00	
	Spec 8C, Specification for Drilling and Production Hoisting Equipment (PSL 1 and PSL 2) (Modified)		\$125.00	
	RP 51, Onshore Oil and Gas Production Practices for Protection of the Environment		\$73.00	
	RP 59, Recommended Practice for Well Control Operations		\$118.00	
	RP 74, Occupational Safety for Oil and Gas Well Drilling and Servicing Operations		\$59.00	
	RP 75, Development of a Safety and Environmental Management Program for Offshore Operations and Facilities		\$86.00	

☐ Payment Enclosed ☐ P.O. No. (Enclose Copy) _____

☐ Charge My IHS Account No. _____

☐ VISA ☐ MasterCard ☐ American Express

☐ Diners Club ☐ Discover

Credit Card No.: _____

Print Name (As It Appears on Card): _____

Expiration Date: _____

Signature: _____

Subtotal

Applicable Sales Tax (see below)

Rush Shipping Fee (see below)

Shipping and Handling (see below)

Total (in U.S. Dollars)

★ To be placed on Standing Order for future editions of this publication, place a check mark in the SO column and sign here:

Pricing and availability subject to change without notice.

Mail Orders – Payment by check or money order in U.S. dollars is required except for established accounts. State and local taxes, \$10 processing fee, and 5% shipping must be added. Send mail orders to: **API Publications, IHS, 15 Inverness Way East, c/o Retail Sales, Englewood, CO 80112-5776, USA.**

Purchase Orders – Purchase orders are accepted from established accounts. Invoice will include actual freight cost, a \$10 processing fee, plus state and local taxes.

Telephone Orders – If ordering by telephone, a \$10 processing fee and actual freight costs will be added to the order.

Sales Tax – All U.S. purchases must include applicable state and local sales tax. Customers claiming tax-exempt status must provide IHS with a copy of their exemption certificate.

Shipping (U.S. Orders) – Orders shipped within the U.S. are sent via traceable means. Most orders are shipped the same day. Subscription updates are sent by First-Class Mail. Other options, including next-day service, air service, and fax transmission are available at additional cost. Call 1-800-854-7179 for more information.

Shipping (International Orders) – Standard international shipping is by air express courier service. Subscription updates are sent by World Mail. Normal delivery is 3-4 days from shipping date.

Rush Shipping Fee – Next Day Delivery orders charge is \$20 in addition to the carrier charges. Next Day Delivery orders must be placed by 2:00 p.m. MST to ensure overnight delivery.

Returns – All returns must be pre-approved by calling the IHS Customer Service Department at 1-800-624-3974 for information and assistance. There may be a 15% restocking fee. Special order items, electronic documents, and age-dated materials are non-returnable.

THERE'S MORE WHERE THIS CAME FROM.

API provides additional resources and programs to the oil and natural gas industry which are based on API Standards. For more information, contact:

API MONOGRAM® LICENSING PROGRAM

Phone: 202-962-4791
Fax: 202-682-8070
Email: certification@api.org

API QUALITY REGISTRAR (APIQR®)

- > ISO 9001 Registration
- > ISO/TS 29001 Registration
- > ISO 14001 Registration
- > API Spec Q1® Registration

Phone: 202-962-4791
Fax: 202-682-8070
Email: certification@api.org

API PERFORATOR DESIGN REGISTRATION PROGRAM

Phone: 202-682-8490
Fax: 202-682-8070
Email: perfdesign@api.org

API TRAINING PROVIDER CERTIFICATION PROGRAM (API TPCP™)

Phone: 202-682-8490
Fax: 202-682-8070
Email: tpcp@api.org

API INDIVIDUAL CERTIFICATION PROGRAMS (ICP®)

Phone: 202-682-8064
Fax: 202-682-8348
Email: icp@api.org

API ENGINE OIL LICENSING AND CERTIFICATION SYSTEM (EOLCS)

Phone: 202-682-8516
Fax: 202-962-4739
Email: eolcs@api.org

API PETROTEAM (TRAINING, EDUCATION AND MEETINGS)

Phone: 202-682-8195
Fax: 202-682-8222
Email: petroteam@api.org

API UNIVERSITY™

Phone: 202-682-8195
Fax: 202-682-8222
Email: training@api.org

Check out the API Publications, Programs, and Services Catalog online at www.api.org.



Copyright 2008 - API, all rights reserved. API, API monogram, APIQR, API Spec Q1, API TPCP, ICP, API University and the API logo are either trademarks or registered trademarks of API in the United States and/or other countries.



1220 L Street, NW
Washington, DC 20005-4070
USA

202.682.8000

Additional copies are available through IHS
Phone Orders: 1-800-854-7179 (Toll-free in the U.S. and Canada)
303-397-7956 (Local and International)
Fax Orders: 303-397-2740
Online Orders: global.ihs.com

Information about API Publications, Programs and Services
is available on the web at www.api.org

Product No. G7HU11